Name: Russell J. Mullins Certifies.

That I am a Licensed Land Surveyor of the State of California;

That a survey was prepared under my supervision and direction in

Tract No. 5104-2, consisting of placing the subdivision monuments;

That said subdivision Map was filed on June 20, 19 75

in Book 82, Page 52 &53 of Map Book in the office of the Recorder of Riverside County, California;

That the following data shown on said Subdivision Map is incorrect and is corrected as follows:

In lieu of finding a 1" iron pipe, a brass tack and L.S. Tag No. 3712, was found at the top of the concrete curb, on a projection of the tract boundary and/or the lot lines at the following points:

The Southwest corner of Lot 19,

The Southeast corner of Lot 20,


The intersection of the right of way lines of Rutland Avenue and the Southerly tract boundary.

There are no fee property owners affected by this correction.

No. 37/2 State of California **NOTARY PUBLIC** SAN BERNARDING COUNTY **CALIFORNIA** County of San Bernardino My Commission Expires May 14, 1977 On November 12, 1975 __, before me, the undersigned, a Notary Public in and for said County and State, personally appeared Lussell. known to me to the person____ whose name_ scribed to the within instrument and acknowledged that executed the same. WITNESS my hand and official seal. Signature ames Celetta James Notary Public (name typed or printed) My Commission Expires May 14, CITY ENGINEER'S CERTIFICATE

This certificate of correction has been examined by the undersigned and such examination disclosed that the only change shown was to correct ion shown on said

ce that was omitted of the land which



<u>Martinek</u> le City Engineer

iam D. Gerdne

C.C.-1

m.B. 87/52-53

62205